

# artisan EXTERIOR

## Geotech Summary

	Weight	Density	Size Tolerance		Slip Resistance	Strength		Absorption	
	30mm /m2	/m3	Dimension	Thickness		Compressive Strength	Flexural Strength	Water Absorption %	Open Porosity %
<b>Limestone</b>									
<b>Caras</b>	78	2.6	+/- 2mm	+/- 2mm	P5	66 MPa	6.33 Mpa	1.34%	2%
<b>Hiekka</b>	78	2.6	+/- 2mm	+/- 2mm	P5	105 MPa	15.4 MPa	0.91%	2.02%
<b>Hiven</b>	81.6	2.72	+/- 2mm	+/- 2mm	P4	126 MPa	18.2 MPa	0.26%	2.67%
<b>Kahvi</b>	78	2.6	+/- 2mm	+/- 2mm	P4	105 MPa	15.4 MPa	0.91%	2.02%
<b>Matala</b>	81	2.7	+/- 2mm	+/- 2mm	P5	117 Mpa	13.9 Mpa	2.13%	3.45%
<b>Nevoa</b>	78	2.6	+/- 2mm	+/- 2mm	P5	66 MPa	6.33 Mpa	1.34%	2%
<b>Olive</b>	81	2.7	+/- 2mm	+/- 2mm	P5	117 Mpa	13.9 Mpa	2.13%	3.45%
<b>Platina</b>	78	2.6	+/- 2mm	+/- 2mm	P4	66 MPa	6.33 Mpa	1.34%	2%
<b>Sokeria</b>	78	2.6	+/- 2mm	+/- 2mm	P5	105 MPa	15.4 MPa	0.91%	2.02%
<b>Marble</b>									
<b>Almendra</b>	80	2.6	+/- 2mm	+/- 2mm	P5	85 Mpa	22 Mpa	1.24%	2.42%
<b>Argento</b>	81	2.7	+/- 2mm	+/- 2mm	P4	56 Mpa	14 Mpa	0.10%	1.10%
<b>Escura</b>	81	2.7	+/- 2mm	+/- 2mm	P5	52 Mpa	14 MPa	0.15%	1.14%
<b>Harmaa</b>	81	2.7	+/- 2mm	+/- 2mm	P5	52 Mpa	14 MPa	0.15%	1.14%
<b>Pantera</b>	81	2.7	+/- 2mm	+/- 2mm	P4	138 Mpa	20 Mpa	0.10%	0.10%
<b>Tempest</b>	82.2	2.74	+/- 2mm	+/- 2mm	P5	109 Mpa	14.51 Mpa	0.05%	0.18%
<b>Valas</b>	80	2.6	+/- 2mm	+/- 2mm	P4	52 Mpa	14 MPa	0.15%	1.14%
<b>Travertine</b>									
<b>Premium Silver</b>	74	2.68	+/- 2mm	+/- 2mm	P4	66.33 Mpa	8.31 Mpa	0.67%	3.0%
<b>Valo</b>	78	2.59	+/- 2mm	+/- 2mm	P3	85.27 Mpa	11.3 Mpa	0.93%	3.0%
<b>Granite</b>									
<b>Aalto</b>	81	2.7	+/- 2mm	+/- 2mm	P5	191.5 Mpa	15.6 Mpa	0.30%	0.90%
<b>Carbon</b>	86	2.87	+/- 2mm	+/- 2mm	P5	174 Mpa	18.9 Mpa	0.16%	0.45%
<b>Carrick</b>	87	2.9	+/- 2mm	+/- 2mm	P5	205.7 Mpa	22.2 Mpa	0.14%	0.40%
<b>Highland Grey</b>	87	2.9	+/- 2mm	+/- 2mm	P5	205.7 Mpa	22.2 Mpa	0.14%	0.40%
<b>Raven</b>	90	3	+/- 2mm	+/- 2mm	P5	141 Mpa	24 Mpa	0.14%	0.41%
<b>Bluestone</b>									
<b>Virtaava</b>	84	2.8	+/- 2mm	+/- 3mm	P5	132.6 Mpa	21.2 Mpa	1.07%	0.60%

For more information contact your Artisan Exterior Account Manager or call 1300 301 898

[www.artisanexterior.com.au](http://www.artisanexterior.com.au)